

# BEARING STORAGE BEST PRACTICES




# LUDECA

Label bearings by type, size, bearing number and date stored.  
Label shelves in accordance with in-house MRO guidelines.


Maintain constant temperature and relative humidity.



Store in clean environment to prevent ingress contamination.




Use oldest bearings first (FIFO).




Use sealed bearings within 5 years of manufacture date.




Keep bearings in their protective packages until ready to use.



If removed from factory packaging, cover with clean lint-free rag.



Lay them on a flat surface (possible deformation if hung or standing on side). Flip periodically.



If bearing is dropped, do not put back on the shelf (do not use!).



Store bearings in vibration free environment.

